

CS-HDM5X1SW3

RS232 commands:

Baud rate: 9600bps

1. HDMI 1 input: port0R
2. HDMI 2 input: port1R
3. HDMI 3 input: port2R
4. HDMI 4 input: port3R
5. HDMI 5 input: port4R
6. Power ON: poweronR
7. Power OFF: poweroffR